

**Illinois Commerce Commission
Pipeline Safety
Field Trip Report**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Randy Carmack	Total Man Days: 3
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller Company Representative's Email Address: mfuller2@ameren.com	Emailed Date: 10/31/2013

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Macomb	Donald Hankins	Macomb	1	10/1/2013	Chris Juliusson, Randy Carmack
Design Testing and Construction	Macomb	Donald Hankins	Macomb	2	10/2/2013, 10/3/2013	Randy Carmack

Statement of Activities

On October 1-3, 2013, a construction audit and a field audit were conducted at Ameren Illinois, in Macomb, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

On October 1, 2013 an Ameren crew was installing anodes on to a section of 2 inch steel main, at East Adams Street and North Monroe Street in Macomb, Illinois. The crew dug up the main and took a cathodic reading, with the reading being -.81. Ameren installed two 17 pound anodes to the main with the reading going to -.87. The crew then went to North Edwards Street & East Adams Street and installed two more 17 pound anodes with the reading before they were installed was -.79, and after installation the main read -.87. Staff was informed that Ameren will inform the corrosion department as to what the readings were.

Staff then observed the Ameren crew replacing isolated service lines, with the service line checklist being included with this report.

ISSUE(S) FOUND:

NO ISSUES FOUND.

ISSUE(S) CORRECTED:

NO ISSUES CORRECTED.

NOTICE OF AMENDMENT(S) FOUND:

NO NOAs FOUND.

NOA(S) CORRECTED:

NO NOAs CORRECTED.

NOTICE OF PROBABLE VIOLATION(S) FOUND:

NO NOPVs FOUND.

NOPV(S) CORRECTED:

NO NOPVs CORRECTED.